OUT56306

P 292119Z
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUITLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2AF BARKSDALE AFB LA
BT
S E C R E T CITE NPIC 5082.

1965 JUL 29 21 41Z

3 0 JUL 1965

History

SEC BR Pads

PSD

PSD-ICB

OS ADMIN

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI)

- 1. CAMERA B 7 WAS USED IN MISSION 8033 FLOWN ON 28 JULY 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.
 - 2. ORIGINAL NEGATIVE:
- A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY HAZE.
- B. 9R SIDE: BOTH FILM EDGES CONTAIN CAMERA ROLLER INDUCED STATIC DISCHARGES. THE OUTBOARD EDGE ALSO CONTAINS INTERMITTENT SMALL EDGE STATIC DISCHARGES. FRAME 1800 IS DEGRADED BY NUMEROUS PINHOLES AND SCRATCHES. A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 1968.
- C. 9L SIDE: INBOARD CAMERA ROLLER INDUCED STATIC DISCHARGES ARE PESENT THROUGHOUT THE FILM. A HEAT SPLICE IS POS-ITIONED BETWEEN FRAMES 298/299 AND A MANUFACTURER'S SPLICE IS PRESENT IN FRAME 809. FRAME 900 CONTAINS A HANDLING ABRASION.
 - D. BOTH SIDES: THE TITLED FRAMES ARE NUMBERED 0000 TO 2223.

Declassification Review by NGA/DoD



- -2 -
- E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.
 - 3. POSITIVE
 - A. THE PI SUITABILITY IS GOOD IN CLOUD FREE AREAS.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS AND/OR HAZE OBSCURE OR DEGRADE APPROXIMATELY 60 PERCENT OF THE TERRAIN COVERED IN THIS MISSION. GP-1. SECRET

-END OF MESSAGE-